

ATTACHMENT 5

SITE PHOTOS



Existing and proposed customer entrance location



View from the middle of the parking lot (looking south)

ATTACHMENT 5



Parking along the southern side of the building (door to be removed; gate to be replaced)



Example of landscaping along Newport Boulevard (woodchips to be replaced with plants)